

Newman

OK 1589

RECEIVED
EPA REGION VI

1985 AUG 22 PM 1:15

AUG 21 1985

SUPERFUND BRANCH

Mr. Don Hensch, Director
Industrial Waste Division
Waste Management Service
Oklahoma State Department of Health
Post Office Box 53551
Oklahoma City, Oklahoma 73152

Re: Total Petroleum
EPA I.D. No. OKD057705972

Dear Mr. Hensch:

Enclosed is a copy of the inspection report completed by Region 6 during its overview inspection at Total Petroleum on July 29-30, 1985. Possible violations found at this facility include:

A. TSD FACILITIES CHECKLIST

1. Security

- ° Facility does not provide adequate security to minimize the possibility for unauthorized entry of persons or livestock onto the active portions of the facility.

40 CFR §265.14 / OSDH 7.3.1 pg. 11 (Class I)

2. Operating Record

- ° Location and quantity of each hazardous waste not recorded on a map or diagram of each cell or disposal area.

40 CFR §265.73(b)(2) / OSDH 7.1.6 pg. 17 (Class I)

B. GROUNDWATER MONITORING

The groundwater report is being reviewed by Elizabeth Pintar, Environmental Engineer, who will provide the comments on the Groundwater Recovery System. A copy of this report will be mailed to you at a later date.

SUPERFUND FILE

OCT 22 1992

REORGANIZED

Based on the nature of the preceeding violations, EPA would issue this facility a RCRA §300B Warning Letter.

Should you have any questions or comments, or disagree with our recommendation, please feel free to contact me at (214) 767-9730 or have your staff contact Rosemary Martinez (214) 767-9865.

Sincerely yours,

William H. Taylor, Jr., Chief
Enforcement Section (6AW-HE)

Enclosure

bcc: Enforcement File

R. Brown 6AW-HC

P. Hull 6AW-HP

D. Olschewsky 6AW-HT

D. Peters 6ES-SH

B. Hanneschlager 6AW-SH

6AW-HE:RMARTINEZ:rlh:8/15/85:Ltr to DHENSCH:Disk 1:TOTAL PETROLUUM: